Installation & Service Instructions for 1-056-X00* Series (all revisions) Manual Adjust Brakes

*This sheet includes Series 1-056,000; 1-056,100; 1-056,200; 1-056,300; 1-056,400; 1-056,500; 1-056,600 and 1-056,900. For other series consult factory.

> LATION AND SERVICE SHEET OF IN LABEL INSIDE OF HOUSING BEFORE

> > Amps Inrush

Amps holding

REVISION CONTROL (if applicable) and brake serial number

(LR 6254

Serial number

36155C

iertz

Please read these instructions carefully before

installing, operating, or servicing your Stearns

Brake. Failure to comply with these instructions

could cause injury to personnel and/or damage

to property if the brake is installed or operated

incorrectly. For definition of limited warranty/lia-

bility, contact Rexnord Industries, LLC, Stearns

Division,5150 S. International Dr., Cudahy, WI


1. Installation and servicing must be made

in compliance with all local safety codes

including Occupational Safety and Health

Act (OSHA). All wiring and electrical con-

nections must comply with the National Electric Code (NEC) and local electric



the use of suitably designed and installed *HazLoc* equipment. When questions arise consult local *Authority Having Jurisdiction (AHJ)*.

- To prevent an electrical hazard, disconnect power source before working on the brake. If power disconnect point is out of sight, lock disconnect in the *off* position and tag to prevent accidental application of power.
- 4. Make certain power source conforms to the requirements specified on the brake nameplate.
- Be careful when touching the exterior of an operating brake. Allow sufficient time for brake to cool before disassembly. Surfaces may be hot enough to be painful or cause injury.
- Do not operate brake with housing removed. All moving parts should be guarded.
- Installation and servicing should be performed only by qualified personnel familiar with the construction and operation of the brake.
- 8. For proper performance and operation, only genuine Stearns parts should be used for repairs and replacements.
- After usage, the brake interior will contain burnt and degraded friction material dust. This dust must be removed before servicing or adjusting the brake.

DO NOT BLOW OFF DUST using an air hose. It is important to avoid dispersing dust into the air or inhaling it, as this may be dangerous to your health.

a) Wear a filtered mask or a respirator while removing dust from the inside of a brake.

b) Use a vacuum cleaner or a soft brush to remove dust from the brake. When brush-

P/N 8-078-905-60 effective 06/14/11

For replacement parts refer to sheets:

Sheet Part No.
8-078-906-00
8-078-906-01
8-078-906-02
8-078-906-03
8-078-906-04
8-078-906-05
8-078-906-06
8-078-906-09

Also available at www.stearns.rexnord.com

ing, avoid causing the dust to become airborne. Collect the dust in a container, such as a bag, which can be sealed off.

10. Caution! While the brake is equipped with a manual release to allow manual shaft rotation, the motor should not be run with the manual release engaged, to avoid overheating the friction disc(s).

General Description

These series of brakes are spring-set, electrically released. They contain one or more rotating friction discs (4) driven by a hub (16) mounted on the motor or other shaft.

Note: Fan-guard mounted brakes requiring IP54 & IP55 protection may require additional sealing measures beyond seals provided with this brake. Pressurized sprays aimed at the fan and brake hub surfaces can result in fluid migration along the motor shaft and keyway, and into the brake. The use of an appropriate sealant such as *RTV* or a *forsheda* seal is advised.

Operating Principle

These series contain one or more friction discs (4) assembled alternately between the endplate (2) friction surface, stationary disc(s) (3) and pressure plate (also called stationary disc) (3). The stationary disc(s) are restrained from rotating by being keyed into the endplate. With the brake released, all disc pack components are free to slide axially and the friction disc(s) to rotate.

Brake release occurs when the solenoid coil is electrically energized, causing the solenoid plunger to travel a specified distance and through a lever system, overcoming the pressure spring force. This action releases the clamping force on the disc pack, thereby allowing the friction disc(s) and brake hub to rotate.

Brake sets and torque is produced when electric current to the solenoid coil is interrupted, thereby collapsing the solenoid magnetic field. The solenoid plunger returns to its original de-energized position allowing the lever arm to move forward by virtue of the compressed torque springs. This action compresses the disc pack components which applies a retarding torque to the brake hub and ultimately restores the brake to a spring-set static condition.

 Use of this brake in atmospheres containing explosive gases and dusts must be in accordance with NEC article 501. This brake is not suitable for use in certain atmospheres containing explosive gases and dusts. *HazLoc* inspection authorities are responsible for verifying and authorizing

Stearns'

105605100XXX

MODEL NUMBER

Mounting

Rexnord Industries, Inc., Steams Divisio Cudahy, WI 53110 (414) 272-1100

Refer to actual nameplate on brake for additional information

53110, (414) 272-1100.

codes in effect.


Torque lb-i


Volts

Note:

Important

Caution






Reconnect coil and replace housing per installation instructions, page 2.

VERTICAL SPRING ASSEMBLY 1-056-X00

Vertical Brake Assembly

Single disc brakes are universal mount and do not require separator springs. Double disc brakes are universal mount but require separator springs which are preassembled to the stationary disc. These discs are inserted spring first into the brake. Refer to figure 5A below.




Installation Procedure for 20 and 25 lb-ft brakes if mounted vertical to motor shaft (These brakes are

factory assembled for horizontal operation.) Remove support plate by loosening the three mounting screws.

Remove stationary discs and friction discs. Using the spring kit provided with this brake, insert three springs of identical color into each stationary disc hole. Springs are inserted from the side opposite the indent mark (see Figure 5B). Stationary disc should be placed on a clean flat surface with a clearance hole to allow the tip of the spring to extend through the bottom side of the stationary plate. Using the 1/8" pin provided and a hammer, drive the spring until the large coil diameter bottoms out against the disc.

Reassemble the disc pack with the stationary discs in the proper arrangement shown in Figure 5C.

Mount support plate and torque screws evenly to 55-58 lb-in.



TORQUE ADJUSTMENT

Torque Adjustment

Brake is factory set for nominal rated static torque which is maximum torque. Torque may be decreased up to 50% for increased stopping times up to 2 second stop time.

The torque on the 1-1/2 lb-ft brake may not be reduced.

Turn both spring adjustment screws (11), Figure 6, equal amounts counterclockwise to decrease torque. See Table A for torque reduction permissible amounts.




Figure 6

TABLE A

Nominal Static Torque (Ib-ft)	Original Spring Height (inches)	Maximum Counter- clockwise Turns	% Torque Reduction per Turn
1-1/2	1.69"	-	-
3	1.47"		
6	1.47"		
10	1.53"	7	7%
15	1.53"		
20	1.53"		
25	1.47"		

TROUBLESHOOTING

COIL	FAILURE
SUPPLY VOLTAGE CAUSE	SUPPLY VOLTAGE CORRECTION
Line voltage >110% of coil rating	Reduce voltage or replace with proper rated coil
AC input on a DC coil	Replace rectifier or replace with proper rated coil.
Excessive voltage drop during inrush time	Increase current rating of power supply.
WIRING CAUSE	WIRING CORRECTION
Leadwires interfering with plunger pull-in	Reroute wiring away from plunger and other moving components.
Excessive voltage drop during inrush time	Increase leadwires size from power supply
Coil leadwire shorted to ground	Replace coil or leadwire and protect with wire sleeving
SOLENOID ASSEMBLY CAUSE	SOLENOID ASSEMBLY CORRECTION
Plunger not seating flush against solenoid frame	Loosen solenoid mounting screws and reposition frame to allow full face contact
Plunger cocked in coil preventing pull-in	Realign solenoid frame
Excessive solenoid/plunger wear at mating surface	Replace solenoid assembly
Broken shading coils	Replace solenoid assembly
WORN PARTS CAUSE	WORN PARTS CORRECTION
Excessive wear of solenoid link arm and/or shoulder bolt	Replace link arm and link bolt; also inspect plunger thru-hole for elongation
Plunger guides worn down and interfering with plunger movement	Replace guides
APPLICATION CAUSE	APPLICATION CORRECTION
Machinery cycle rate is exceeding brake rating	Reduce brake cycle rate or use alternate control method
High ambient temperature (>110%) and thermal load exceeding coil insulation rating	Use Class H rated coil and /or find alternate method of cooling brake
Brake coil wired with windings of an Inverter motor or other voltage/current limiting device	Wire coil to dedicated power source with instantaneous coil rated voltage
MISCELLANEOUS CAUSE	MISCELLANEOUS CORRECTION
Wrong or over tightened torque	Replace with proper spring or refer to Installation section for proper spring height
Excessive air gap	Reset, refer to Installation Section 4

EXCESSIVE WEAR / OVERHEATING			
AIR GAP CAUSE	AIR GAP CORRECTION		
Low solenoid air gap	Reset air gap (refer to Air Gap Adjustment)		
Disc pack dragging	Inspect endplate, hub and discs for dirt, burrs, wiring and other sources of interference preventing disc "float"		
CYCLE RATE CAUSE	CYCLE RATE CORRECTION		
Brake "jogging" exceeding coil cycle rate	Reduce cycle rate or consider alternate control method		
Thermal capacity is being exceeded	Reduce cycle rate, use alternate control method or increase brake size		
ALIGNMENT CAUSE	ALIGNMENT CORRECTION		
Broke endplate not concentric to motor C-Face	Motor register must be within .004" on concentricity.		
Motor shaft runout is excessive	Must be within .002"; runout; consult motor manufacturer		
Brake is being operated on a incline greater than 15° above or below horizontal	Vertical separator springs must be used to prevent discs from becoming cocked		
WORN PARTS CAUSE	WORN PARTS CORRECTION		
Friction disc excessively worn (disc can wear to 1/2 original thickness or .093")	Replace friction discs.		
Endplate, stationary disc or pressure plate warped	Replace warped or worn component		
Linkages and/or pivot pins worn	Replace all worn components		
Motor shaft endfloat excessive	Endfloat must not exceed .020"; consult motor manufacturer		
HUB CAUSE	HUB CORRECTION		
Burr on hub interfering with disc "float"	File off burr		
Set screw backed out and interfering with disc	Retighten set screw; use Loctite® 242 to help secure		
MISCELLANEOUS	MISCELLANEOUS		
Solenoid plunger not pulling completely	Check line voltage (±10% of nameplate rating) or replace worn solenoid assembly		
Wiring is restricting disc pack movement	Reroute wiring		
Excessive stop time (2 seconds or greater)	Increase brake size/torque or use alternate control method		
High Ambient temperature	Reduce cycle rate or use alternate		

method of cooling

Rexnord Industries, LLC, Stearns Division, 5150 S. International Dr., Cudahy, WI 53110, (414) 272-1100 Fax: (414) 277-4364 www.stearns.rexnord.com

(in excess of 110°F)